
### Power Failure in CNC Machines?

**Causing:** Tool Breakage, Production Loss and Job Rejection



# Install ACCUSTOP Axis Drop Preventer today!

Suitable for all types of CNC & Grinding Machines
Prevents gravity axis drop, ensures emergency stop
during power fail



Visit Now


#### **How ACCUSTOP Works**

Senses 3-phase power input, cuts off brake-voltage in advance during power failure. Prevents gravity axis drop of CNC and Grinding machines.



## **Key Advantages**

- Sensing of power failure & phase imbalance
- Auto emergency creation during failure
- Max. 5 contacts supported
- Compact design, easy wiring
- Mounts inside electrical panel
- Manual emergency interface
- No changes in CNC systems & parameters
- Customization as per your CNC machine



#### **RK CNC SOLUTIONS**

# rkcncsolutions.com

- #23/5, Near Yashas Vidya Kendra Masthappa Layout, Somashettihalli, Chikabanavara Post, Bangalore – 560 090
- ☑ rkcncsolutions@gmail.com | ⑤ ⑤ 9741497292 / 9741985519